## Lloyds Auctioneers & Valuers Inspection Report

dentification No: 101054	Date: 12-4-11
GETTETTICATION TOURS.	
· · · · · · · · · · · · · · · · · · ·	
$Q_{-}$	7R15
Vehicle Make:	7K15
575	SPORTSMAN
I O La Caraca a secretaria secretaria de la caraca de la	
R41 V Keys:	***
Speedo/Hours: 425	
•	
Colour: BLACK/WHITE	~~ <
	50003012
Vin/Chassis No: HXADAH5TIE	7141640 - 50003012
Engine No: $N / \sqrt{1}$	
570 Silvetons \	Compliance Plate Date: 2015
Capacity: Cylinders:	Compilative Face Page.

## What We Check:

- 1. We visually check the Vehicle/Motorcycle/Watercraft for general wear and tear on components.
- 2. Start and run engine (if possible) and check for obvious abnormal noises or poor running (We will not dismantle the engine in any way).

## What We Don't Check:

- 1. Oil and fuel consumption.
- 2. Source of oil or fuel leaks if area is dirty.
  - 3. Internal engine/gearbox condition.
- 4. The vehicle does not undergo a road/water test.

The report on the condition of the above vehicle/motorcycle/watercraft is made with all care taken on the basis of a visual check only of the items listed in this inspection report.

This report is not a warranty or guarantee for any purpose and is only valid on the inspection date. To the extent permitted by law, we exclude all conditions and warranties that may be implied by law.

CODE	ITEM CHECKED	COMMENTS	<u> </u>	[ Good	Fair.	Mepair
1	Engine Visual Condition					
2	Chassis/Frame/Hull	· · · · · · · · · · · · · · · · · · ·		4.	V	
3	Suspension Front				V	
Ą	Suspension Rear				~	
5	Brake Pads Front	Approximately 30 Percent			<u></u>	
6	Brake Pads Rear	Approximately - Percent			1	
7	Tyres Front	Approximately 50 Percent		1		
8	Tyres Rear	Approximately 50 Percent		1	11. ord.	J.
9	Battery			V		
10	Steering			1.	~	<u> </u>
11.	Drive Chain & Sprockets	CVT	-		2 7 1 6	
12	Wheels & Discs				V	
13	Drive Work or Plastics				1	-
14	Lights & Switches			1		
15	Handle Bars, Foot Pegs & Levers				~	
1.6	Exhaust System	ti .			سا	
17	Damage & Scratches					

Engine: Starts & Rui	ns: Winds over but will not start:	Will not wind over:

Inspection Comments:
CORROSION AROUND FRAME,
SUSPENDIAN ENGINE + ELECTRICS, STA WHEET
DAMPNER LORRODED
Please note: These vehicles do sit sometimes for an extended period of time before they are offered for sale and this is the usual cause for
flat batteries and starting problems due to stale or old fuel.