



Vehicle History Summary



Fleet #	ADT26
Registration	
Make	Caterpillar
Model	740
VIN / Chassis #	CAT00740AB1P03605
Build Date	2008

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-2485	30/10/2023		198106	STRUT ADJUST	4341- ADJUSTED BOTH POS 1 & POS 2, STRUTS TO HEIGHT, 650-670MM	BRAD
R-2414	21/10/2023		19781	hydraulic oil leak	REPAIR REPORT 4260 - REMOVED HOIST CONTROL VALVE & RESEAL VALVE - REFIT VALVE & TESTED OK , REMOVED BRAKE PUMP & RESEAL - REFIT & TESTED OK	Russell Wilks
R-2374	06/10/2023		19779	OIL LEAK	5596- RAN MACHINE TO GET HOT OPERATED CHECKED HOSES FOR LEAKS FOUND HOIST CONTROL VALVE WEEPING NOT WORTH REPLACING SEALS CHECKED & TIGHTENED BOLTS, REPLACED 3 X HOSES BETWEEN ARTIC, REWRAPPED COIL AROUND HOSES & FASTENED,	BRAD, GARETH, PAYDEN
R-2373	03/10/2023		19775	VARIOUS REPAIRS	4313- MISSING DRIVERS SEAT, REFITTED SEAT, STEER COLOUM ADJUSTER, REFITTED COLUM ADJUSTER, REFITTED 2 WAY FITTED EXHAUST TIP, FITT 2 WAY ARLEC EXT, ADJUST POS 2 STRUTS, REMOVE & REPLACE 3 HYDRAULIC HOSES, INSPECT OIL WEEP,	BRAD, BRAD
R-2372	28/09/2023			LEAK	4310-LIFTED CAB CLEANED, FOUND SMALL LEAK,	LEE GOODALL
R-2054	01/08/2023		19768	OIL LEAK	3788-STARTED TRUCKS DROVE THEM AROUND TO GET THEM HOT, WORKED TIPPER BODY, PARKED & INSPECTED FOR OIL LEAKS, TIGHTENED ANY LOOSE FITTINGS, MOST OIL SPOTS WERE RESIDUE CLEANED OFF WITH BRAKE CLEANER,	BRAD , PAYDEN
R-1926	14/07/2023		19768	REMOVE TAILGATE FOR TRANSPORT	3780-REMOVE TAILGATE FOR TRANSPORT, HOOKED UP COMPUTER TO FIND GEARSHIFTER FAULT CODE, FOUND THE ALARM WAS NOT PLUGED IN ONCE PLUGED IN LIGHT ON DASH WENT OUT, BELEIVE THEY WERE HERE FOR 1 HOUR PLUS TRAVEL,	BRAD, LEE

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-1910	14/06/2023		19768	TYRE	3757-SWAP LH REAR TYRE FROM ADT 26 TO LH FRONT OF ADT 31 & THEN ADT 31 LH FRONT TO RH FRONT OF ADT 27, DIDNT HAVE ENOUGH STANS & HAD JACKING ISSUES,	BRAD MILLER , GREAME, PAYDEN
R-2454	13/06/2023		19768	SPACER PLATES	3762- HAD TO PURCHASE 5MM STEEL PLATE TO CUT TO SIZE FOR SPACERS IN TAIL GATE HAD ISSUES WITH MAGNETIC DRILL WHILST DRILLING HOLES, FITTED SPACER PLATES PUT TAILGATE BACK TOGETHER,	GREAME, PAYDEN
R-1909	05/06/2023		19768	VARIOUS REPAIRS	3754-INSTALL NEW STRUT FROM ADT 31, TRUCK BATTERY FLAT HAD TO JUMP START BONNET STUCK DOWN, REGAS STRUTS, CHANGE OVER GEAR SHIFT LEVER TO REMOVE FAULT, FAULT STILL CAME UP -SWAPPED FROM ADT 27, CHANGED UP DOWN SWITCH ON THE SEAT AS I WAS LEAKING, STILL LEAKING BELEIVE MAYBE THE BAG LEAKING, PART NO- KAB-MT-KV-S VALVE,	BRAD MILLER , PAYDEN
R-1908	30/05/2023		19768	TAIL GATE	5749-INSTALL TAILGATE HAD TO TRIM THE TIPPEES PIN LENGTH SO HE TAILGATE CAN SHUT,	BRAD MILLER , PAYDEN
R-1907	29/05/2023		19768	STRUTS	5748-DISSASSEMBLE STRUT & NUT ON P SHAN SHAFT WAS DIFFICULT TO UNDO 5-6 HRS TO UNDO BY 1 INCH RATTLE GUN UPON REMOVAL FOUND THREAD WAS NO GOOD IP P, SSHAN SHAFT, CLEAN DOWN ALL STRUTCOMPONETS,	BRAD MILLER , PAYDEN
R-1906	27/05/2023		19768	STRUTS	5747- HEATED STRUT BEARING AFTER HAD COOLED OVER NIGHT, PIN CAME OUT,	BRAD MILLER , PAYDEN
R-1905	25/05/2023		19768	STRUTS	5745- WOULDNT START HAD TO PUT FUEL IN TRUCK, STARTED REMOVING STRUT HAVING ISSUES WITH THE BOTTOM PIN STUCK IN HAS MOVED 5MM, WILL MAKE PULLER TOMORROW TO REMOVE, PINS SEIZED IN STRUT BEARING HAVE TRIED HEATING AROUND BEARING,	BRAD MILLER , GREAME, LEE, PAYDEN
R-1904	20/05/2023		19768	STRUTS	5739-STARTED REGASING STRUTS,	BRAD MILLER , Russell Wilks
R-1903	19/05/2023		19768	STRUTS	5737- DRAIN OIL OUT OF STRUTS, READY TO REGAS,	BRAD MILLER , Russell Wilks
R-1597	08/05/2023		19768	A FRAME	5719- CLEANED BOLT REMOVED DIRT, RUST & GREASE, INSTALLED BEARING INTO A FRAME, INSTALLED SUSPENSION A FRAME ,	BRAD MILLER , PAYDEN

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-1463	27/04/2023		19768	LOCKING PIN	5714- INSTALL NEW LOCKING PIN INTO CABIN ROPS PINS X3 - 103-5798	BRAD MILLER
R-1462	26/04/2023		19768	A FRAME	5711- REMOVED FRONT LOWER A FRAME, HAD TO HIRE HYDROLIC POWER PACK TO JACK FRAME OFF THE PIN, BEARING FELL OUT ONCE OFF THE PIN - NEEDS LINE BORING	BRAD MILLER
S-1841	24/04/2023		19768	A - 250hr	5710- REPLACED TRANS FILTER - 1R - 0719, REPLACED & PRIMED FUEL FILTERS - 326-1644 & 1R - 0762, FILLED TRANSMISSION 72LITRES -SAE 30, FILLED ALL DIFFS 63LITRES EACH -SAE 50, FILLED STEER TANK 97 LITRES HD 68- FILLED HOIST TANK 233 LITRES HD 68, REPLACED TRANSMISSION DRAIN PLUG - 1381- 1509, REPLACED REAR DIFF DRAIN PLUG -5P4484, REPLACED HYDROULIC FILTERS X 5 - 132-8876, STARTED REMOVING LOWER AFRAME, TO RELPLACE ARCHIIICE BEARING ,	BRAD MILLER
R-1459	24/04/2023		20961	TRANSMISSION FAULT	4254- CONNECT LAPTOP & FOUND ACTIVE TRANSMISSION FAULT, TRANSMISSION SHIFT CONTROL LEVER HIGH VOLTAGE, ONGOING JOB - CHANGE LEVER WITH ANOTHER ONE FROM SPARE TRUCK ,	Russell Wilks
S-1837	22/04/2023		19768	A - 250hr	5709- DRAINED ALL OILS EXEPT FINAL DRIVES, REPLACED ENGINE OIL FILTER, REPLACE DROP BOX FILTER, REFILLED ENGINE OIL WITH 38 LITRES AFP E900 SAE 15W -40, REFILLED DROP BOX OIL WITH 20 LITRES, C4 SAE 30 ,	
R-1422	21/04/2023		20961	BRAKE HOSE	4253- REMOVE BRAKE FEADING HOSE & GET PIRTEKTO MAKE NEW HOSE, FIT HOSE BACK ONTO MACHINE & FIT NEW SPIRAL WRAP TO ALL HOSES TO TIDY UP ,	Russell Wilks
R-1421	19/04/2023		19768	HYDROLIC HOSE	5700- WRAP HYDROLIC HOSES, FIT REFLECTIVE TAPE, FIT CIRCUIT NUMBERS, FIT STEERING BLADES ,	BOB, BRAD MILLER , Russell Wilks
R-1420	19/04/2023		19768	VARIOUS REPAIRS	5702- FINISH INSTALLING UHF, INSTALL RADIO, MOUNT REVERSE CAMERA, FIT RADIATOR CAP, REMOVED REAR WIPPER BLADE OF ADT 24 & INSTALLED ON ADT 26, REMOVED FRONT WINDOW HANDLE OFF ADT 24 & INSTALLED IN ADT 26, REMOVED STEERING COLUM SHRUB OFF ADT 27 & INSTALLED ON ADT 26, REMOVED DOOR PULL HANDLE OFF ADT 24 & INSTALLED ON ADT 26, INSTALLED ALL PLASTICS DOOR CARD /DASH ETC ,	

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-1419	18/04/2023		19768	VARIOUS REPAIRS	5695- TRACED & REMOVED COILED WIRES, FOUND REAR LIGHTS HAD BEEN UNPLUGGED ALONG WIRING LOOM, RE-INSTALLED REAR TAILLIGHT UNITS, REPAIRED WIRING FOR WORK LIGHTS, MADE NEW FLASHING LIGHT BRACKET & INSTALLED NEW ONE WITH BOLTS BELOW, INSTALL NEW FIRE EXTINGUISHER BRACKET, 1 M8 BOLT & NUT AS BELOW REMOVED FIRE EXTINGUISHER FROM ADT 30 TO USE IN ADT 26, RAN WIRING READY FOR UHF TO BE MOUNTED ,	BRAD MILLER
R-1405	18/04/2023		20961	Tail light	5697- FOUND ORIGNIAL TAILLIGHT IN WORKSHOP & FITTED TO TRUCK, REMOVE TAILLIGHT OFF ADT 30 & FITTED TO ADT 26, REMOVED REVERSE LIGHT FROM ADT 30 & FITTED TO ADT 26, REPAIRED WIRING FROM CHASSIS TO REAR LIGHT GROUP ,	Russell Wilks
R-1404	18/04/2023		20961	EMERGENCY STOPS	5698- FITTED OUTSIDE EMERGNCY STOP ON L/H MUD GAURD & WIRED UP ,	Russell Wilks

Signed: _____

Name: _____

Date: _____