



Vehicle History Summary



Fleet #	GRD01
Registration	
Make	CAT
Model	140M Series
VIN / Chassis #	CAT0140MCB9D00682
Build Date	2008

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-2783	14/12/2023			RAGS- EXPOXY	2337845- RAGS 10 KG COLOURED COMMERCIAL CLEANING RAGS, DEVCON FASMETAL 10 EPOXY REPAIR PUTTY 184G	
R-2682	13/11/2023		16530	coolant leak	6206- PUT CHEMI WELD IN RADIATOR TO SEAL UP HOLES & STOP COOLANT LEAKS,	Jason
R-2401	14/09/2023			HOSE BLOWN	0661- TRAVELLED TO SITE, HOSE HAD BEEN INSTALLED BY MAKEKADI MECHANIC, RE ASSEMBLED ALL PARTS REMOVED, OXY HEAT BASH PLATE & STRAIGHTEN PRIOR TO INSTALLING FUEL TANK, RE-FILL HYD TANK & FUEL, RUN & TEST, CHECK FOR LEAKS, RE-FIT REMAINING PARTS, PACK TOOLS & TRAVEL BACK TO GRIFFITH,	RIVERINA MECHANICAL
R-2400	14/09/2023			BLOWN HOSE	0661- INSPECT GRADER HYD LEAK, HOSE BLOWN INSIDE GOOSE NECK, DRAINED FUEL, REMOVED PARTS REQUIRED TO ACCESS HOSE, INCLUDING FUEL TANK STEP, TOP HYD BANK COVER, TYRE & REAR ENGINE BAY COVERS, IDENTIFY BLOWN HOSE, REMOVED REQUIRED CLAMPS IN ORDER TO HAVE HOSE REMOVED, WEATHER HALTED FURTHER REPAIRS, PACK TOOLS TRAVELLED BACK TO GRIFFITH,	RIVERINA MECHANICAL
R-2201	23/08/2023			REPAIR FUEL SYSTEM	1713316-SERVICE CALL OUT TO FIX FUEL SYSTEM GR01	Westrac

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-2200	19/06/2023		15768	VARIOUS REPAIRS	4496-TRY TO REMOVE SHOES IN CIRCLE FRAME, BOLTS SEIZED & BRAKING WHEN LOOSEING, LEAVE OLD WEAR STRIPS ON CIRCLE SHOES & ADJUST, REMOVE TOP WEAR STRIPS & SHIM UP TOP OF BLADE, REPLACE BOTTOM BEARING CUPS ON BLADE LIFT CYLINDERS, FIT LEFT HAND SIDE CYLINDER BEARING ON ARTICULATION CYLINDERS, CHECK OVER MACHINE, STILL HAS FIVE ACTIVE GPS CODES BEING LAGGED ALL THE TIME, TOPCAN NEEDED TO RECTIFY FAULTS,	NATHAN GEORGE, Russell Wilks
R-2199	18/06/2023		15739	VARIOUS REPAIRS	4640-REPLACED LHS ARTIC BUSHES & DISSASSEMBLE RHS, DIAGNOSE TRANS OIL LEAK FOUND & ORDER SEAL TO FIX LEAK, RESHIMING BLADE SWIVEL ORDERED SHIMS,	NATHAN GEORGE
R-2198	16/06/2023		15973	LADE ADJUSTMENT	4491- REPLACE TOP & BOTTOM BLADE SLIDES & ADJUST BLADE,	ALEX, Russell Wilks
R-2197	15/06/2023		15973	oil leak	4488-REMOVE BLADE SIDE SHIFT CYLINDER, REPLACE ALL SEALS ON PIPE WORK TO CYLINDER, INSTALL & TESTED OK, REPLACE VARIOUS HOSE CLAMPS ON HOSES & TIGHTEN,	ALEX, Russell Wilks
R-2196	13/06/2023		15973	BLADE REPAIRS	4484- REMOVE BOTTOM BLADE SLIDES, ORDER PARTS, STRAIGHTEN GPS POLE,	Russell Wilks
R-2195	22/05/2023			SPARE TYRE	5522- MOUNT TYRE TO SPARE GRADER RIM, CHECK PRESSURE / LEAKS,	ALEX
S-1827	29/03/2023		15417	C - 1000hr	2723- CHANGED ALL OILS & FILTERS - PULL CAB DOORS OFF & STRAIGHTEN DOORS - REPLACE DOOR GLASS	ALEX
R-1399	28/02/2023		15572	RADIATOR HOSE	2703- REMOVE DAMAGED HOSE - REPLACED HOSE, TOP UP WITH WATER	ALEX
S-1826	17/02/2023		15528	A - 250hr	5985- CHECKED OIL LEVELS - GREASED ALL NIPPLES - CHECKED COOLANT - CHECKED LIGHTS - TOPED UP TRANSMISSION OIL,	EMILY
R-1398	18/01/2023		15491	AC REPAIRS	5418994- TRAVEL TO SITE, SYSTEM WORKING OK, EVAPORATOR BLOCKED - SEAT NEEDS TO BE REMOVED TO CLEAN - TRAVEL HOME	WEST WYALONG MACHINERY CENTRE

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-1396	14/12/2022		15448	OIL LEAKS	5254- WORK ON GRADER TO STOP THE OIL LEAK - TOP UP TRANS OIL WITH 20LITRES, MACHINE STOP AGAIN THE OIL LEAK IS BAD, 1 CUT THE PIPE FROM THE TRANS TO THE FILTER, WHERE THE LEAK IS, TOOK TO TUMUT HYDROLIC, MAKE NEW HOSE COME BACK REFITTED MACHINE WORK ,	SALESI TOKI
R-993	08/12/2022	0	0	STEERING		SALESI TOKI
R-982	06/12/2022	0	0	tyres		SALESI TOKI
R-2194	23/11/2022		15346	O-RING	5042- REPLACED O-RING OF THE PIPE FROM THE HYD FILTER TO THE COOLER	SALESI TOKI
R-935	18/11/2022	0	0	Various		SALESI TOKI
R-917	15/11/2022	0	0	MINOR FLUID LEAKS		SALESI TOKI
R-912	06/11/2022	0	0	Various		
R-1397	19/10/2022		15478	CUTTING EDGE	4947- WORK ON THE GREATER CUTTING EDGE ,	SAL
R-906	04/10/2022	0	0	Various		SALESI TOKI
R-894	15/09/2022	0	0	Various		
R-885	29/08/2022	0	15168	tracks, undercarriage		SALESI TOKI
R-887	27/08/2022	0	15179	OIL LEAKS		SALESI TOKI

Signed: _____

Name: _____

Date: _____