



2/7 ACE CRESCENT  
TUGGERAH NSW 2259  
PHONE 02 4352 2044  
MVRL 54706

## Vehicle Condition Inspection Report

Date of Inspection:

Vehicle Make &amp; Model

ROGONOMOBIL

Body Style

COUP

Year

1957

VIN

UNABLE TO SIGHT

Odometer

19801 miles

Summary of overall Vehicle Condition

Good ☒Fair ☐Poor ☐

## Engine/Exhaust

Engine Oil Condition	(Y) / N	Tune Condition	(Y) / N	Fuel System	(Y) / N	Thermostat	Y / (N)
Oil Leaks	Y / (N)	Smoke	(Y) / N	Fuel Leaks	Y / (N)	Exhaust Condition	Y / (N)
Engine Mounts	(Y) / N	Air Filter	(Y) / N	Radiator Hoses	Y / (N)	Exhaust Mounts	(Y) / N
Engine Noises	Y / (N)	Drive Belts	(Y) / N	Water Pump	Y / (N)	Air cooled	
Exhaust Leaks	Y / (N)	Emission System	Y / N	Coolant	Y / (N)		

Comments-

2 stroke

## Transmission/Driveline

Automatic ☐Manual ☒

Transmission	(Y) / N	Mounts	(Y) / N	Clutch Ops	(Y) / N	CV/Universal Joints	(Y) / N
Oil/Fluid Condition	(Y) / N	Noises	Y / (N)	Adjustment	(Y) / N	Drive shaft/Boots	(Y) / N
Shift Operation	(Y) / N	Inhibitor Switch	Y / N	Linkages	(Y) / N	Final Drive	(Y) / N

Comments-

## Steering/Suspension

Power Assistance

Yes ☐No ☒

Steeringbox/Rack	(Y) / N	Power Steering	Y / (N)	Wheel Bearings	(Y) / N	Wheel/Spare	(Y) / N
Oil Leaks	Y / (N)	Shock Absorbers	(Y) / N	Tyre Wear	Y / (N)	Driveability	(Y) / N
Steering Linkage	(Y) / N	Bushes/Pivots	(Y) / N	Tyre Condition	(Y) / N		

Comments-

## Brakes

## Electrical

Operation	(Y) / N	Line Condition	(Y) / N	Wiring	(Y) / N	Windscreen Wipers	(Y) / N
Park Brake	(Y) / N	Hose Condition	(Y) / N	Headlights/Aim	(Y) / N	Battery/Starter Motor	(Y) / N
Fluid Leads	Y / (N)	Pedal Height	(Y) / N	Exterior Lighting	Y / (N)	Charge Rate	(Y) / N
Pads/Lining	(Y) / N	Pedal Rubbers	(Y) / N	Indicators	(Y) / N	Horn	(Y) / N
ABS Check Light	Y / N			Instrumentation	(Y) / N		

Comments-

brake light inop

Ray Bunn 5-2-19

**Body**

Structure ☒ Y ☐ N Previous Repairs Y ☒ N Door Locks ☒ Y ☐ N Seats & Trim ☒ Y ☐ N  
 Corrosion Y ☒ N Windscreen/Glass ☒ Y ☐ N Door/Window Op Y ☐ N Seat Belts Y ☐ N  
 Panel Condition ☒ Y ☐ N Paint Condition Y ☒ N Windows Tinting Y ☐ N Door Handles ☒ Y ☐ N

Comments- Paint average in places

**Miscellaneous**

Demister Y ☒ N Heater Y ☒ N Ability to run on alternative fuels Y ☒ N  
 Air Conditioner Y ☒ N LPG Compliance Y ☒ N Other

Comments- \_\_\_\_\_

**PRE-PURCHASE INSPECTION REPORT TERMS AND CONDITIONS**

**Report is visual only**

1. This pre-purchase inspection report is not undertaken by Gosford Classic Car Museum but by a third party inspector and is based only on a visual and non-mechanical inspection of the condition of the specific items set out in this report form.
2. This report only advises on the condition of the vehicle at the time of inspection.

**What the report does not cover**

3. Supplementary Restraint or Air Bag Systems have been specifically excluded from the inspection due to the complexity of test procedures. Customers who are considering the purchase of a vehicle fitted with an SRS or Air Bag System are advised to refer the vehicle to an authorised service agent for system functionality
4. This report is not a substitute for a roadworthy test, which is a tolerance test. The customer acknowledges that receipt of a satisfactory condition report does not mean the vehicle will also pass a roadworthy test. This report is not a road worthy certificate and cannot be used as a roadworthy certificate.
5. This report does not advise on whether any manufacturer recall notices apply to the vehicle and it is your responsibility to check that the vehicle is not subject to a recall notice.

**Purpose of the Report**

6. You understand that this report is not intended to be a valuation of the vehicle, nor is it intended to be advice whether or not to purchase the vehicle. No warranties are made in relation to the value, performance or adequacy of the vehicle. The decision to purchase a vehicle is your own having regard to such matters as you consider relevant and having regard to your own circumstances and your own investigations and inquiries. Reliance on this report is subject to these terms and conditions.
7. Coastal Automotive Enterprises is not an agent or representative of Gosford Classic Car Museum.

**Limitation of liability**

8. Gosford Classic Car Museum is not responsible for carrying out the inspection, any services connected with such inspection or the contents of this report
9. Gosford Classic Car Museum and Coastal Automotive Enterprises will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection or for any defects that could reasonably be expected to have become evident by the dismantling or removal of parts of the vehicle or by inspection of any items not set out in the report form.
10. Except as expressly provided in this report, all terms, conditions, warranties, guarantees and statements whether express or implied, written, oral, statutory or otherwise, are excluded, other than terms which may by law may not be excluded (including the Australian Consumer Law).
11. To the full extent permitted by law, Gosford Classic Car Museum will only be liable to you pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law that cannot be excluded PROVIDED THAT, to the full extent permitted by law, any such liability of Gosford Classic Car Museum is limited at Gosford Classic Car Museums option to:
  - a. Replace or repair the relevant goods
  - b. Supplying goods equivalent to the relevant goods
  - c. Supplying the relevant services again; or
  - d. Paying the cost of such replacement, repairs or supply
  - e. Governing Law
12. This Report is subject to the laws of the State of New South Wales, Australia.