



Vehicle History Summary



Fleet #	ADT31
Registration	
Make	CAT
Model	740
VIN / Chassis #	CAT00740EB1P03768
Build Date	2008

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-2489	30/10/2023			POS 1	4343- SOURCE PARTS FOR POS 1,	BRAD
R-2429	20/10/2023			WHEEL NUTS	4332- MOVED MACHINE TO PICK UP POINT,	BRAD
R-2428	12/10/2023		20454	OIL LEAK	5599- DROVE TO SITE TO CHECK FOR OIL LEAK FOUND O-RING STARTED PULLING APART AS THEY ARE LARGER HOSES WILL REQUIRE SECOND PERSON, DROVE TO SITE 13/10 CHANGED O-RINGS ON BRAKE COOLING LINE,	BRAD , Russell Wilks
R-2488	04/10/2023		20398	OIL LEAK	5593- DROVE TO SITE FOUND HOIST PILOT LINES WERE LEAKING REMOVED & HAD NO NEW HOSES MADE AT HOSEPOWER, DROVE BACK TO SITE & INSTALLED NEW HOSES REPLACED 2 X ORINGS,	BRAD
R-2391	04/10/2023		20398	OIL LEAK	5593- DROVE TO SITE FOUND HOIST PILOT LINES WERE LEAKING REMOVED & HAD NEW HOSES MADE AT HOSE POWER DROVE BACK TO SITE & INSTALL NEW HOSES REPLACED 2 X O-RINGS,	
R-2380	28/09/2023		20398	HOSE BLOWN	5585- DROVE TO SITE FOR BLOWN HOSE SWAPPED HOSE FROM ADT 24-ADT -31, REPLACED TIPPER HYDRAULIC RETURN LINE BETWEEN ARTIC,	BRAD
R-2276	16/09/2023		20345	VARIOUS REPAIRS	5580-FIX BONNET FIBERGLASS TO THE FRAME 2 X NUT & BOLTS, BLEW OUT AIRFILTER & CABIN FILTER & BLOCK OUTSIDE AIRFILTER, FOUND LOW SIDE A/C PRESSURE WAS DOWN SO RECHARGED HIGH SIDE, GREASED ALL PINS & LINKAGES,	BRAD, Russell Wilks
R-2091	13/08/2023		20310	SEAL KIT	1 X PC SEAL KIT -H.C SUPPLIED - PARTS EMERGENCY FREIGHT	
R-2184	10/08/2023		20310	STEERING RAM	3798- REMOVE RH STEERING RAM SPLIT RAM READY FOR RESEAL, RESEALED STEERING RAM, INSTALL STEERING RAM STARTED TRUCK TO CHECK, NO LEAKS,	BRAD, PAYDEN, Russell Wilks

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-2051	04/08/2023		20310	OIL LEAK	3786-REPLACED SUCTION LINE ON STEER TANK, REPLACED HYDRAULIC LINE OFF STEER TANK, HAD TO DRAIN TANK INTO JERRY CANS TO REPLACE LINES, REMOVED HYDRAULIC HOSES, GOT NEW LINES MADE AT PIRTEK REHUNGE TO SUIT, INSTALLED NEW LINES REFILLED OIL RAN & CHECKED OIL,	BRAD , PAYDEN
R-2050	01/08/2023		20310	OIL LEAKS	3788- STARTED TRUCKS DROVE THEM AROUND TO GET THEM HOT, WORKED TIPPER BODY PARKED & INSPECTED FOR LEAKS, TIGHTENED ANY LOOSE FITTINGS, MOST OIL SPOTS WERE RESIDUE CLEANED OFF WITH BRAKE CLEANER	BRAD , PAYDEN
R-1937	14/07/2023		20310	OIL LEAK	3781-DROVE TO SITE TO CHECK FOR OIL LEAK, CLEAN DOWN OIL FROM AROUND HOSE, STARTED WARMED UP FOUND NO OIL LEAKING, FOUND OIL SITTING ON TOP OF CHASSIS CLEANED OFF BELEIVE WAS THE ISSUE SPLASHING OUT,	BRAD, LEE
R-1936	13/07/2023		20310	VARIOUS REPAIRS	3778-REPLACE FUEL FILTERS & INSTALL NEW FUEL BOWL, HAD TO PUT FUEL INTO TRUCK AS COUDNT PRIME FUEL SYSTEM, INSTALL NEW FIRE EXTINGUISHER WITH BRACKET, REMOVED OLD UNUSED WORK LIGHTS, INSTALL NEW RH FRONT WINDOW HANDLE, REMOVED FROM ADT 27,STICK ON REFLECTIVE STICKERS, CLEAN DOWN INSIDE & OUT,	BRAD, LEE
R-1935	23/06/2023		20310	VARIOUS REPAIRS	3769-THREAD REPAIR CARRIED OUT BY WINELLE HYDROLOGICS, COMPLETE STRUT REBUILD, SEAL KIT SUPPLIED BY HASTINGS, INSTALL LH STRUT HAVE HAD TO HEAT EYELOT WITH OXY FOR THE UPPER PIN TO MOVE, REPLACE UPPER & LOWER BEARINGS, REGANS STRUTS TEST DROVE & RECHECKED RIDE HEIGHT, PUT ON SPIRAL WRAP ON LINES RUNNING FROM CAB TO TIPPER BIN, REPLACE LH / RH LOWER MIRRORS, PUT DASH DOOR CARD ALL BACK TOGETHER REPLACED LH REAR BRAKE & INDICATOR LIGHTS REMOVED FROM ADT 30,	BRAD, GREAME, LEE, PAYDEN
R-1934	05/06/2023		20310	STRUT	3753-REMOVED LH STRUT TO BE PUT INTO ADT 26,	BRAD, PAYDEN

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
S-2046	31/05/2023		20310	C - 1000hr	3751-SERVICE - ENGINE OIL-15W-40- 40 LITRES, ENGINE OIL FILTER -1R-1808, TRANSMISSION OIL-SAE 30-72 LITRES, TRANSMISSION FILTER -1R 0719, TRANSFER OIL SAE 30-18 LITRES, TRANFER CASE FILTER -1G-8878, DIFFERENTIAL OILS SAE-50 -65 LITRES, EACH 195 LITRES, HYDROLIC OIL 15D 68-97 LITRES -STEER & BRAKE 233LITRES-HOIST, GASSED STRUTS, TEST DROVE REMEASURED HEIGHTS,	
R-1933	24/05/2023		20310	STRUT	5744-INSTALL STRUT LH SIDE,	BRAD, LEE
R-1932	12/05/2023		20310	STRUT	5730-STRIP DOWN STRUT SEALS, BEARINGS ECT, & PUT NEW KIT THROUGH, SENT OF BARREL TO HAVE BEARING HOUSING LINE BOARD - NORWELD,	BRAD, PAYDEN , Russell Wilks
R-1931	12/04/2023		20310	ARM REST	5683-REMOVE ARM REST OFF SEAT TO FIT SEAT FOR ADT 24, BOLTS WERE SEIZED UP & HARD TO REMOVE	BRAD MILLER
R-1930	04/04/2023		20310	GREASE LINES	5673- REPLACE RH UPPER STRUT GREASE LINE	BRAD MILLER
R-1392	31/03/2023		20310	AC REPAIRS	5668- CONNECTED GAUGES & FOUND NO GAS IN SYSTEM, EVACUATED SYSTEM & TESTED HELD NEGATIVE PRESSURE, CHARGED SYSTEM WITH R134A GAS & PIAG OIL, SEALED UP EVAPORATOR AIR BOX WITH TACKY TAPE, SYSTEM CYCLING & TESTED OK - LABOUR SUPPLIED BY FULNOISE AUTO ELECTRICAL,	Russell Wilks
R-1391	31/03/2023		20310	AM/FM RADIO	5667- INSTALL NEW AM/FM RADIO & AERIAL - LABOUR SUPPLIED BY FULNOISE AUTO ELECTRICAL ,	Russell Wilks
R-1390	31/03/2023		20310	UHF AERIAL	5666- INSTALL NEW UHF RADIO & AERIAL - PARTS SUPPLIED BY J A S - LABOUR SUPPLIED BY FULNOISE AUTO ELECTRICAL ,	Russell Wilks
R-1389	31/03/2023		20310	EMERGENCY STOPS	5665- INSTALL INTERNAL EMERGENCY STOP, INSTALL EXTERNAL EMERGENCY STOP ON L/H WHEEL ARCH - PARTS SUPPLIED BY J A S - LABOUR SUPPLIED BY FULNOISE AUTO ELECTRICAL	Russell Wilks

Signed: _____

Name: _____

Date: _____